



PO Box 1150
Issaquah, WA 98027
(206) 965-5797

J. Jeffrey Huber Daily Report

10-21-2020

River Activities – None.

Construction Activities – Electron Crew working on placing rocks, welding sheet piles, and erosion control.

JH – 0700 Electron crew member Bruce conducting water quality monitoring.

JH – 0700 electron crew begins putting in rip rap. The rip rap is than filled with fines and smaller rock to ensure no voids.

JH – 0700 Electron crew member is downstream 300' to monitor turbidity. Water from the excavation has not been communicating with the river. Water is not communicating today. No issues.

JH – 0900 Electron crew laying down organic wood chips around the site to cover exposed earth. This will be an ongoing thing for the next few days.

JH – 0900 Electron crew is setting 12"x 12" wood beams 10' long to buffer the center abutment from damage from rocks. Electron crew is grouting the center abutment holes left from the forms.

JH – 1100 Electron crew refreshing BMP's.

JH – 1200 Pierce County Drone Crew on the North side of the Puyallup River.

JH - 1400 Electron crew installing rip rap and back filling with smaller rock and fines. No issues.

JH – 1500 Electron crew cleaning up around the center abutment.

JH – 1530 – 1830. Went to the North side of the Puyallup river. Checked the fish ladder. Observed fish greater than 12" (Red, Purplish) in the fish ladder heading upstream.

Sincerely,



PO Box 1150
Issaquah, WA 98027
(206) 965-5797

J. Jeffrey Huber
Encore Environmental
Independent Compliance Monitor on Behalf of Pierce County
Electron Hydro